
ASSEMBLY INSTRUCTION


ITEM#: 67443

DESCRIPTION: ARM CHAIR


Thank you for purchasing this quality product. Be sure to check all packing materials carefully for small parts may have come loose inside the carton during shipment. Identify and count all parts and compare with the parts listed below.

PARTLIST:





HARDWARE LIST				
NO.	Drawing	Description	Q'ty	
Α	OF THE REAL PROPERTY.	Bolt (Φ5/16"×3-1/4")	4pcs	
₿	(Decree)	Bolt (Φ5/16"×2-1/2")	4pcs	
C	(A)	Bolt (Φ5/16*×1-3/4*)	3pcs	
D	0	Flat washer (Ø5/16*x19mm)	Hiper	
E	0	Spring washer (Ø5/16*)	Hipc	
F	==3	Ø5/16* Wrench(12mm)	1pc	
G	-	Screw (Ф8x1-1/2")	2pcs	



CLEANING INSTRUCTION

Clean the surface of the Arm Chair with furniture polish and a soft cloth.

Made in Vietnam

ASSEMBLY INSTRUCTION


ITEM#: 67443

DESCRIPTION: ARM CHAIR


Thank you for purchasing this quality product. Be sure to check all packing materials carefully for small parts may have come loose inside the carton during shipment. Identify and count all parts and compare with the parts listed below.

PART LIST:





		HARDWARE LIST	
NO.	Drawing		Q'ty
A	(a) \$10.000 (b)	Вок (Ф5/16"×3-1/4")	4pcs
:8	(DEE)	Bolt (Φ5/16"×2-1/2")	4pcs
C	(Heren	Bolt (Φ5/16*×1-3/4*)	3pcs
D	<u></u>	Flat washer (Ø5/16'x19mm)	llpcs
E	0	Spring washer (Ø5/16")	11pcs
F	<u></u>	Ø5/16* Wrench(12mm)	1pc
G	(married	Screw (@8x1-1/2*)	3



CLEANING INSTRUCTION

Clean the surface of the Arm Chair with furniture polish and a soft cloth.

Made in Vietnam