


## ASSEMBLY INSTRUCTION

Step 2:





Step 3:



G B C

Finish:



## Hardware List

No.:	Description	Drawing	Size	Q' ty
Α	Bolt		Ø <sup>5</sup> ⁄ <sub>16</sub> "X1"	4
В	Lock Washer	<b>©</b>	Ø <sup>5</sup> ⁄ <sub>16</sub> "X12mm	8
С	Flat Washer	0	Ø <sup>5</sup> ⁄ <sub>16</sub> X19mm	8
D	Allen Wrench		5mm	1
E	Screw	<b>JIIIII</b>	8X <sup>3</sup> <sub>4</sub> "	5
F	Screw	) <del>-</del>	3*12	8
G	Bolt	8	Ø5/ <sub>16</sub> "X1-1/2"	4
Н	Fasten unit		44mmX20mm	12
1	Screw	<b>Junno</b>	Ø7mmX38mm	12
J	Screw	)mm»	Ø6mmX16mm	12
К	Shrink bolt		Ø5/16"X1-1/2"	12
L	Safty belt		8mmX250mm	6