








# ASSEMBLY INSTRUCTION

Step 1:

53130



## Hardware List:

No.:	Description	Drawing	Size	Q'ty
A	Middle Bolt		Ø5/16" X2-1/2 "	8
B	Lock Washer		Ø5/16" X12mm	8
C	Flat Washer		Ø5/16" X22mm	8
F	wood tenon		φ 5mm	1