

ASSEMBLY INSTRUCTION

Step 1:



Finish:



Hardware List:

No.:	Description	Drawing	Size	Q' ty
Α	Middle Bolt		Ø5/16" X2-1/4 "	4
В	Lock Washer	©	Ø5/16" X12mm	9
С	Flat Washer	©	Ø5/16" X22mm	9
D	Long Bolt		Ø5/16" X3-1/4 "	4
Е	Short Bolt	(Cananana)	Ø5/16" X2"	1
F	Allen Wrench		5mm	1