

ASSEMBLY INSTRUCTION

Step 1:



Finish:



Hardware List:

No.:	Description	Drawing	Size	Q' ty
Α	Middle Bolt		Ø5/16" X2 "	4
В	Lock Washer	©	Ø5/16" X12mm	11
С	Flat Washer	0	Ø5/16" X22mm	11
D	Long Bolt		Ø5/16" X3-1/2 "	4
Е	Short Bolt		Ø5/16" X1-3/4 "	3
F	Wood Screw	()111117 -	Ø8X1-3/4 "	2
G	Allen Wrench		5mm	1