

ASSEMBLY INSTRUCTION


Step 1:








Step 3:



Finish:



No.:	Description	Drawing	Size	Q' ty
Α	Middle Bolt		Ø5/16" X2-1/4 "	12
В	Lock Washer	©	Ø5/16" X12mm	12
С	Flat Washer	©	Ø5/16" X22mm	12
D	Allen Wrench		5mm	1