



ASSEMBLY INSTRUCTION


Step 1:



Step 2:



Finish:



Hardware List:

| No.: | Description | Drawing | Size | Q'ty |
|------|-----------------|---------|---------------|------|
| A | Bit | | #5/16"X1-1/4" | 3 |
| B | Lock Washer | | Ø6/16"X12mm | 3 |
| C | Flat Washer | | Ø6/16"X22mm | 3 |
| D | Allen Wrench | | Ø6mm | 1 |
| E | Wood Screw | | 7"X12mm | 8 |
| F | Metal Corner | | 18X18X16 | 4 |
| G | Pine | | Ø6 | 4 |
| H | Wood Screw | | 8X1" | 4 |
| I | Connecting Bolt | | Ø13X23mm | 4 |
| J | Connecting Nut | | Ø13X20mm | 4 |
| K | Allen Wrench | | Ø4mm | 2 |